



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

| TC APPROVAL | FAA APPROVAL | EASA APPROVAL | AIRCRAFT TYPE | DESCRIPTION | AFM | ICA |
|---|---------------------------|--------------------------|---|---|--|--|
| STC | | | | | | |
| SA18-51 Issue 1 Apr 26, 2018 | - | - | DHC-6-1, -100, -110, -200, -210, -300, -310, -320, -400 | Installation, Rudder Improvement | None | E121531 Rev - Jan 30, 2018 |
| SA17-81 Issue 1 Aug 15, 2017 | - | - | DHC-6-100, -110, -200, -210, -300, -310, -320 | Installation of LED Replacement Cockpit Panels | None | E115899 Rev - Aug 4, 2017 |
| SA17-78 Issue 2 Feb 5, 2018 | SA040033NY Jan 2, 2018 | - | DHC-6-100, -110, -200, -210, -300, -310, -320 | Replacement, LED Master Caution Panel | E108530 Rev - Aug 15, 2017 | E108531 Rev B Aug 9, 2017 E108532 Rev B Aug 9, 2017 |
| SA17-29 Issue 1 Apr 10, 2017 | SA03926NY Jun 9, 2017 | - | DHC-6-400 | Fold Up Utility Seats | None | E114231 Rev - Apr 7, 2017 |
| SA16-45 Issue 1 Apr 12, 2016 | SA03757NY Jul 15, 2016 | - | DHC-6-100, -110, -200, -210, -300, -310, -320, -400 | Installation of Replacement Fuel Manifold Tubes | None | None |
| SA15-49 Issue 1 Jul 9, 2015 | - | - | DHC-6-100, -200, -300 | Radar Altimeter Mounts (Structural Provisions Only) | None | None |
| SA15-44 Issue 1 May 28, 2015 | SA03868NY Feb 21, 2017 | 10059728 Oct 11, 2016 | DHC-6-100, -200, -300 | Fuel Quantity Indication System Replacement | None | E110331 Rev B Jul 10, 2017 E110332 Rev A Mar 29, 2016 |
| SA14-61 Issue 2 Feb 6, 2017 | - | - | DHC-6-100, -200, -300 | Installation of Dual LCR-100 Attitude Heading Reference System (AHRS) | E110940 Rev A Feb 3, 2017 E110930 Rev A Feb 3, 2017 | E110941 Rev A Feb 1, 2017 E110931 Rev A Feb 1, 2017 |
| SA13-38 Issue 1 Jun 5, 2013 | SA03363NY Feb 27, 2014 | - | DHC-6-100, -200, -300 | Installation of Universal Avionics TAWS, Class A | E108030 Rev - Jun 4, 2013 | E108031 Rev A Jan 7, 2014 |
| SA13-37 Issue 1 Jun 19, 2013 | - | - | DHC-6-100, -200, -300 | Installation of Universal Avionics EFI-890R PFD | E103530 Rev B Mar 1, 2017 | E103531 Rev C May 23, 2017 |
| SA13-27 Issue 1 Aug 27, 2013 | - | - | DHC-6-1, -100, -110, -200, -210, -300, -310, -320, -400 | Barrier Net Installation | 293490 Rev A Aug 27, 2013 | 293430 Rev B Nov 13, 2013 |



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

| TC APPROVAL | FAA APPROVAL | EASA APPROVAL | AIRCRAFT TYPE | DESCRIPTION | AFM | ICA |
|-------------------------------------|---------------------------|--|-----------------------|--|--|--|
| SA12-13 Issue 2 Dec 23, 2015 | - | 10047440 Dec 12, 2013 | DHC-6-100, -200, -300 | Installation of Electronics International MVP-50T Engine Dispal System | E101530 Rev C Aug 15, 2017 | E101531 Rev A May 10, 2012 (SA12-13 Issue 1 only) |
| | | | | | | E111531 Rev A Sep 22, 2017 |
| | | | | | | E111532 Rev - Dec 15, 2015 |
| SA11-80 Issue 1 Nov 14, 2011 | SA03150NY Oct 3, 2012 | 10040247 Jun 19, 2012 | DHC-6-100, -200, -300 | Installation of either Universal Avionics CVR-120A or CVR-120R Cockpit Voice Recorder | None | E103131 Rev B Aug 8, 2012 |
| SA11-79 Issue 1 Oct 12, 2011 | SA03346NY Nov 22, 2013 | 10038966 Mar 27, 2012 | DHC-6-100, -200, -300 | Installation of Dual or Single Garmin GTN-650 or GTN-750 GPS/NAV/COMM | E102930 Rev A Dec 1, 2016 | E102931 Rev B Nov 25, 2016 E102932 Rev - Nov 25, 2016 |
| SA11-72 Issue 1 Aug 23, 2011 | - | 10037908 Jan 5, 2012 | DHC-6-100, -200, -300 | Installation of Engine Chip Detectors | E104630 Rev A May 2, 2016 | E104631 Rev A Feb 10, 2016 |
| SA10-24 Issue 3 May 21, 2013 | SA03357NY Dec 12, 2013 | - | DHC-6-100, -200, -300 | Installation of L-3 Communications ESI-1000 Electronic Standby Indicator, or L-3 Communications GH-3900.2 Electronic Standby Instrument System (ESIS), or Mid-Continent Instruments 4200-10 Standby Attitude Indicator, or Mid-Continent Instruments 4300-411 Standby Attitude Indicator | E100130 Rev - Jun 25, 2010 | E100131 Rev B Nov 19, 2013 |
| | | | | | E100132 Rev A Jul 5, 2010 | E100133 Rev A Sep 19, 2013 |
| | | | | | E100134 Rev - Mar 29, 2010 | E100135 Rev A Sep 19, 2013 |
| | | | | | E100145 Rev B Sep 1, 2017 | E100146 Rev C Sep 1, 2017 |
| SA08-38 Issue 2 Jun 20, 2008 | - | EASA.IM.A.S.02878 Rev 1 Dec 17, 2008 | BEECH | Installation of Pitot Heat Indication System | FMS-1270-02 Issue 1 Jun 20, 2008 | MMS-1270-02 Issue 1 Jun 2, 2008 |
| | | | DHC-6-100, -200, -300 | | | FMS-1270-01 Issue 1 Apr 7, 2008 |
| SA07-131 Issue 2 Mar 12, 2010 | - | EASA.IM.A.S.02729 Aug 13, 2008 | DHC-6-100, -200, -300 | Installation of Single or Dual Sandel SN4500 primary navigational display(s) (EHSI) with optional SA4550 primary attitude display(s) (EADI) | E100030 Rev A Nov 18, 2016 | E100031 Rev B Nov 9, 2016 |
| | | 10016400 Rev 1 Aug 3, 2010 | | | E100032 Rev B Nov 18, 2016 | E100033 Rev B Nov 9, 2016 |



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

| TC APPROVAL | FAA APPROVAL | EASA APPROVAL | AIRCRAFT TYPE | DESCRIPTION | AFM | ICA |
|--|---------------------------|--|-----------------------------|--|---|---|
| SA07-65 Issue 5 Jun 2, 2017 | SA03275NY Apr 29, 2013 | - | DHC-6-100, -200, -300, -400 | Installation of Supplemental Oxygen Systems | E104330 Rev C Dec 21, 2018 | E104331 Rev E Nov 09, 2018 |
| | | | | | E106830 Rev - May 26, 2017 | E106831 Rev - Nov 15, 2016 |
| SA07-59 Issue 1 May 7, 2007 | - | - | DHC-6-100, -200, -300 | Elevator and Rudder Access Panels | None | MMS-1206-01 Issue 1 May 3, 2007 |
| SA06-53 Issue 1 Nov 14, 2006 | SA03923NY Jun 6, 2017 | - | DHC-6-100, -200, -300 | Installation of Avionics Shelves In Tail | None | None |
| SA06-45 Issue 1 Jul 11, 2006 | - | - | BEECH 200 | Installation of a L-3 Communications - Avionics Recorders (Fairchild) A100S, or FA2100, or Universal CVR -30B Solid State Cockpit Voice Recorder (CVR) | None | 195631 Rev - Feb 13, 2006 |
| SA05-54 Issue 2 Mar 19, 2012 | SA02204NY Jan 10, 2006 | 10042836 Dec 20, 2012 | DHC-6-100, -200, -300 | Installation of A L-3 Skywatch HP TCAS 1 System | E101430 Rev A Apr 19, 2013 | E101431 Rev A Jan 26, 2013 |
| SA04-52 Issue 1 Nov 2, 2004 | SA02561NY Sep 2, 2008 | - | BEECH 99 SERIES | Sandel ST3400 Terrain Awareness Warning System (TAWS) / RMI System | 193730 Rev A Aug 25, 2008 | 193731 Rev A Jul 24, 2008 (FAA) 193732 Rev - Jun 29, 2004 |
| | | | | | | |
| SA02-128 Issue 3 Sep 26, 2012 | SA01869NY Mar 16, 2004 | EASA.IM.A.S.02129 Nov 3, 2006 | DHC-6-100, -200, -300 | Installation of a Single or Dual Sandel ST3400 Terrain Awareness Warning System (TAWS) / RMI System | E100330 Rev - Sep 14, 2012 | E100331 Rev A Apr 10, 2013 |
| | | 10015977 Rev 1 Mar 17, 2010 | | | (EASA) E100372 Rev A Sep 20, 2011 | |
| SA02-119 Issue 4 Dec 18, 2007 | SA01885NY Mar 30, 2004 | EASA.IM.A.S.02581 Rev 1 Nov 21, 2008 | DHC-6-1, -100, -200, -300 | Dual or Single Garmin GNS 530 / 530W or GNS 430 / 430W GPS / Nav / Comm system(s) for IFR Enroute, Terminal and Approach Operations | (Non-WAAS) 181830 Rev C Sep 14, 2005 | (Non-WAAS) 181831 Rev C Sep 1, 2005 |
| | | | | | (WAAS) 181833 Rev A Feb 10, 2017 | (WAAS) 181834 Rev - Sep 21, 2007 |
| | | | | | (FAA) 181832 Rev A Apr 23, 2004 | (FAA) 181835 Rev - Sep 21, 2007 |
| SA02-98 Issue 1 Sep 4, 2002 | - | - | DHC-6-100, -200, -300 | Aft Equipment Shelf Installation | None | None |



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

| TC APPROVAL | FAA APPROVAL | EASA APPROVAL | AIRCRAFT TYPE | DESCRIPTION | AFM | ICA |
|--|---------------------------|-----------------------------------|---|--|------------------------------------|---|
| SA02-25 Issue 1 Mar 15, 2002 | - | - | DHC-6-100, -200, -300 | Purge Hose Replacement | None | None |
| SA02-1 Issue 5 Jun 14, 2012 | SA02387NY May 31, 2007 | - | DHC-6-100,- 200, -300 | Installation, Substitute Passanger Cabin and Cargo Baggage Floor Panels | None | E105331 Rev - Mar 16, 2012 |
| SA01-135 Issue 1 Oct 31, 2001 | - | - | DHC-6-100, -200, -300 | Elevator Replacement Trailing Edge | None | None |
| SA01-76 Issue 1 Jun 27, 2001 | SA01673NY May 14, 2003 | - | DHC-6-100, -200 | Installation of Pratt & Whitney PT6A-34 Engines with either Hartzell HC-B3TN-3D(Y) / T10282N(B) Propellers or McCauley RHFR34C764/94LMB-0 Propellers | FMS323101 Rev 2 Jun 27, 2001 | MMS323101 Rev 1 May 30, 2001 |
| SA01-30 Issue 2 Sep 27, 2016 | SA02384NY May 21, 2007 | EASA.IM.A.S.02198 Dec 22, 2006 | DHC-6-100, -110, -200, -210, -300, -310, -320 | Removal Of Auxiliary Battery | None | E118010 Rev - Aug 10, 2016 |
| SA01-17 Issue 3 Jun 9, 2016 | - | EASA.IM.A.S.02199 Oct 10, 2008 | DHC-6-300 | Cabin Evacuation Lighting Control System Change | E114030 Rev - Jun 8, 2016 | None |
| SA98-67 Issue 1 Jun 29, 1998 | - | - | Beech 99, 99A, A99, A99A | Installation of a Fairchild A100 or A100A Cockpit Voice Recorder | None | None |
| SA97-101 Issue 4 Oct 23, 2007 | SA02297NY Aug 31, 2006 | EASA.IM.A.S.02202 Oct 22, 2007 | DHC-6-100, -200, -300 | Cockpit Voice Recorder Installation | None | 199031 Rev C Dec 10, 2015 (FAA) 199032 Rev C Dec 10, 2015 |
| SA97-77 Issue 2 Nov 20, 2001 | - | - | DHC-6-100, -200, -300 | Replace Upper Fuselage Skin Panel | None | None |
| SA96-123 Issue 4 Mar 10, 2017 | SA00837NY May 14, 1998 | - | DHC-6-100, -200 | Install Pratt & Whitney PT6A-27 Engines | D32891 Rev B Mar 9, 2017 | D32871 Rev A Jan 27, 2017 |
| SA96-110 Issue 1 Aug 1, 1996 | SA03265NY Mar 27, 2013 | 10045940 Jul 30, 2013 | DHC-6-300 | Installation of PT6A-34 Engines Derated To 620 SHP in Lieu of PT6A-27 Engines | FMS966401 Rev - Aug 1, 1996 | MMS966401 Rev - Aug 1, 1996 |
| SE10-1 Issue 1 Jan 27, 2010 | SE02837NY Aug 27, 2010 | - | PT6A-21 | Conversion of PT6A-21 to PT6A-28 | None | None |