

TABLE 3.0: RDC LIST

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-RA92-017/D b) C-FMYV c) 374	1 2	Jan 28, 1992 May 01, 1992	DHC-6-300	STA 111.0 Skin Joint Repair		
a) C-RA92-018/D b) C-FBQC c)	1	Jan 28, 1992	Beech 60 (Duke)	Loran Antenna Support Repair		
a) C-RA93-054/D b) C-GZGO c) 2017	1	Apr 14, 1993	Britten Norman BN2A-26	Fuselage Repair		
a) C-RA01-003/D b) C-GXVX c) B-18	1	Jan 18, 2001	Beechcraft King Air 100	Main Spar Repair at Left Wing F.S. 78.0		
a) C-RA01-163 b) All c) 6 and subsequent	1	Nov 15, 2001	DHC-6 100,200,300	Trim Cable Pulley Bracket Repair		
a) C-RA01-644/D b) N204SA c) 402	1	Aug 03, 2001	DHC-6-300	Oversize Fasteners on Main Frame Splice		
a) C-RA02-607/D b) C-GHBP c) 380	1	Jan 31, 2002	DHC-6-300	Oversize Fasteners on Upper Main Frame Splice		

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-RA03-078/D b) All c) 6 and subsequent	1	Aug 22, 2003	DHC-6 100,200,300	Fuel Tube Repair		
a) C-RA03-079/D b) All c) 6 and subsequent	1	Aug 29, 2003	DHC-6 100,200,300	Bracket Assembly Repair		
a) C-RA03-080/D b) All c) 6 and subsequent	1	July 16, 2003	DHC-6 100,200,300	Jack Pad Repair		
a) C-RA03-418/D b) All c) All	1	Dec 01, 2003	DHC-6 100,200,300	Repair of LH & RH Wing Flap Hinge Arm		
a) C-RA04-386/D b) All c) All	1	Nov 19, 2004	DHC-6 100,200,300	Replacement of Aluminum Power Wires between the generator relay and the left & right firewalls		
a) C-RA06-254/D b) All c) All	1	Aug 11, 2006	DHC-6 100,200,300	Control Surface Tip Weld Repair		
a) C-RA06-255/D b) All c) All	1	Aug 11, 2006	DHC-6 100,200,300	Generator Cooling Duct Assembly Repair		

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-RA07-396/D b) All c) All		Dec 31, 2007	DHC-6 100,200,300	Repair of Elevator End Rib PN C6TE1062-27 and C6TE1026-29		
a) C-RA08-055/D b) All c) All	1	Apr 03, 2008	DHC-6 100,200,300	Bleed Air Duck Repair		
a) W-RA95-034/D b) C-FTJJ c) 325	1 2 3	Mar 27, 1995 Oct 4, 1995 Mar 20, 1996	DHC-6-300	Wing Assembly Repair		
a) W-RA97-039D b) C-GQKZ c) 532	1	May 16, 1997	DHC-6-300	Wing Repair		
a) W-RA97-139 b) All c) All	1 2	Mar 02, 1998 Jan 21, 2000	DHC-6 100,200,300	Fore Flap Hinge Arm Repair		
a) W-RA97-139/D b) All c) All	1	Mar 02, 1998	DHC-6 100,200,300	Fore Flap Hinge Arm Repair		
a) b) c)						

TABLE 4.0: PDA LIST

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i>	<i>Issue</i>	<i>Issue Date</i>				
PDA02-03	1	Aug 20, 2002	DHC-6 100,200,300	Upper Fuselage Skin Panel (Forward) TCCA-PDA-RMA-330207-1		
PDA02-19	1	Aug 20, 2002	DHC-6 100,200,300	Upper Fuselage Skin Panel (Aft) TCCA-PDA-RMA-976101-11		
PDA07-11	1 2	May 22, 2007 Apr 07, 2011	DHC-6-300	Inboard Leading Edge D-Nose Assembly Replacement, As per eligibility list		
PDA13-4	1	Feb 01, 2013	DHC-6 100,200,300	Replacement Air Conditioning Heating and Cooling Ducts		

TABLE 5.0: LSTC LIST

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number b) Registration c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) W-LSA92-100/D b) CFEQB/CFMHB/ CGEAL c) 31T-7720062/ 31T-7620023/ 31T-7720062	5 (copy)	Dec 22, 1995	Piper PA-31T	A Cloud Seeding System for two types of flares, an end burner flare and an ejectable flare		
a) W-LSA91-095 b) C-FIZD c) 461	1	Jul 19, 1991	DHC-6-300	Avionics Re-fit		
a) W-LSA92-108 b) FISO c) 204	1	1992-06-12	DHC-6	Installation of HF and Compass System.		
a) W-LSA92-129 b) C-FMYV c) 374	1	Aug 10, 1992	DHC-6-300	Avionics Inst. Including Radio Master, Directional Gyro, and Audio Panel		
a) W-LSA93-130/D b) C-FAWC c) 108	1	Sept 30, 1993	DHC-6-100	Baggage Door Installation		
a) W-LSA93-133 b) CFQOV c) B38	1	1993-12-17	Beech 100	Installation of a Trimble TNL-2000T GPS Receiver and ETS 802100-29 CDI.		

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number b) Registration c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA94-246 b) V3-HTA c) 112	1 2	Nov 11, 1994 Dec 20, 1994	DHC-6-200	Installation of Pratt & Whitney PT6A-27 Engines.		
a) C-LSA95-241 b) N10EA, N30EA c) 199, 198	1 2	Nov 11, 1994 Dec 20, 1994	DHC-6-200	Installation of Pratt & Whitney PT6A-27 Engines.		
a) W-LSA96-026/D b) C-FQCN c) U-126	1 (copy)	Mar 21, 1996	Beech 99A	HF Communication System install		
a) W-LSA96-122/D b) C-FRQI c) U-124	2 (copy)	Dec 05, 1996	Beech 99	Install Cockpit Voice Recorder Not RMA LSTC, RMA installation only		
a) W-LSA97-026/D b) C-GBGC c) 701	1	Mar 17, 1997	DHC-6-300	Replacement Fuselage Skin Panel		
a) W-LSA97-130/D b) C-GAWW, C-GAVV, C-GAVU c) U-137, U-142, U-143	1	Dec 04, 1997	Beech 99A	Install Radio Altimeter Antennas		

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) W-LSA97-144/D b) C-GAWW, C-GAVV, C-GAVU c) U-137, U-142, U-143	1	Dec 12, 1997	Beech 99A	Aft Avionics Rack Installation		
a) W-LSA97-150/D b) C-GBEB c) 272	1	Feb 01, 1998	DHC-6-300	Ferry Fuel System		
a) W-LSA97-134/D b) C-GREK c) 31-7612075	3 (copy)	Dec 12, 1998	Piper PA-31	Install Trimble Approach Plus GPS Navigation System NOT RMA LSTC, RMA Install Only		
a) W-LSA98-123/D b) C-FQCN, C-FOZU c) U-126, U-130	1	Dec 20, 1998	Beech 99	Install Phoenix VR-1010-24-2B Voltage Regulators		
a) W-LSA98-124/D b) C-FVCE, C-GAWW, C-GAVV c) U-118, U-137, U-142	1	Dec 20, 1998	Beech 99	Install Phoenix VR-1010-24-2B Voltage Regulators		
a) C-LSA00-174/D b) C-FWUL c) 360	1	May 15, 2000	DHC-6-300	Removal of Auxiliary Battery	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA00-207/D b) C-GXVX c) B 18	1	Jun 29, 2000	Beech 100	Install GA-56 Antennas, FS 153.3, FS 170.7 (Structural Provisions Only)		
a) C-LSA00-233/D b) C-GXVX c) B 18	1 2	Dec 05, 2000 Aug 02, 2000	Beech 100	Install of Dual Garmin GNS 430 NAV/COM/GPS (IFR GPS Enroute, Terminal, Approach) VHF Com & NAV only		
a) C-LSA01-636/D b) C-GHBP c) 380	1	Aug 08, 2001	DHC-6-100	Fastener Replacement on the R/H Wing Spar		
a) C-LSA01-645/D b) C-GBEB c) 272	1	2001-08-14	DHC-6-300	Elevator Trailing Edge Replacement		
a) C-LSA01-646/D b) C-GBEB c) 272	1	2001-09-21	DHC-6-300	Installation of Universal CVR-30B Cockpit Voice Recorder		
a) C-LSA01-652/D b) C-GJDE c) 471	1	2001-09-14	DHC-6-300	Installation of Universal CVR-30B Cockpit Voice Recorder		
a) C-LSA03-137/D b) C-FTXQ c) 308	1	2003-12-31	DHC-6-300	Single GNS 430 GPS/Nav/Comm System Installation		

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number b) Registration c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA05-132/D b) C-FASQ c) 78	1	Jun 06, 2005	DHC-6-100	Propeller Install, Hartzell HC-B3TN-3D(Y)		
a) C-LSA05-198/D b) VP-FBL, VP-FBB, VP-FBC, VP-FAZ c) 839, 783, 787, 748	1 2	Jun 14, 2005 Jul 20, 2007	DHC-6-300	Installation of LITEF GmbH LCR-92S Attitude and Heading Reference System (AHRS) into DHC-6-300		
a) C-LSA05-234/D b) VP-FAZ c) 748	1	Aug 25, 2005	DHC-6-300	MASIN Installation		
a) C-LSA05-360/D b) N48RF c) 740	1 (copy)	Nov 01, 2005	DHC-6-300	Nose Boom Installation		
a) C-LSA07-029/D b) CFTUV, CFTXI CGMAF, CGMAK, CGUMW c) 1020, 1016, 1044, 1107, 1065	1 2 3	2009-05-05	Bombardier CL-215-1A10	Installation of a L-3 SkyWatch HP (TCAS 1) system and a EVS Technology Max Viz EVS-1500 Enhanced Vision System.	-	-
a) C-LSA07-260/D b) CFOPI, CFOPJ, CFOPG c) 243, 344, 232	1	2007-10-10	DHC-6 Series 300	Installation of a Sandel SA4550 Primary Attitude Display.	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number b) Registration c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA09-068/D b) C-FTUV, C-FTXI, C-GMAF, C-GUMW c) 1020, 1016, 1044, 1065	1	2009-03-23	Bombardier CL-215-1A10	Garmin GPS 400W with Shadin ADC-2000 & Garmin GDL-69 Installation	-	-
a) C-LSA09-069/D b) C-FTUV, CFTXI, C-GMAF, CGUMW c) 1020, 1016, 1044, 1065	1	2009-03-23	Bombardier CL-215-1A10	Sandel SN4500 EHSI Installation	-	-
a) C-LSA09-260/D b) C-FTUV, CFTXI/ C-GMAF, CGUMW c) 1020, 1016, 1044, 1065	1	2009-11-10	Bombardier CL-215-1A10	Avionics Upgrade	-	-
a) C-LSA10-061/D b) C-GMAF, c) 1044	1	2010-04-28	Bombardier CL-215-1A10	Relocation of ADF-60B Antenna	-	-
a) C-LSA10-066/D b) C-GTWW c) LJ657	1	2010-04-06	Beech C90	Installation of Sandel ST3400 TAWS/RMI, Class B	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number b) Registration c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA10-065/D b) C-GTWW, C-FHLL c) LJ657, LJ1111	1	2010-04-06	Beech C90 RAYTHEON C90A	For S/N LJ-657, Deviations to FAA STC SA01552CH-D for the installation of the L-3 Communications Skywatch HP TCAS I System, Model SKY899 For S/N LJ-1111, Upgrade existing SKY497 to SKY899.	-	-
a) C-LSA10-083/D b) C-FHLL c) LJ1111	1	2010-05-25	Raytheon C90A	Installation of Universal Avionics CVR-30B	-	-
a) C-LSA10-192/D b) C-GCUP c) E2096	1	2010-09-08	BAE 146-200	Installation of Dual Honeywell GNS-XLS FMS	-	-
a) C-LSA10-213/D b) C-GCVS c) BL13	1	2010-10-19	Hawker Beechcraft 200C	Deviations to FAA STC to install Garmin GPS-400W. (Western Avionics project)	-	-
a) C-LSA10-250/D b) C-GKEE c) 3308	1	2010-12-10	Aero Commander 500-S	Installation of Avidyne EXP-5000 PFD	-	-
a) C-LSA10-251/D b) C-FKJI, C-GJLI, C-GQNJ c) BB105, BB347, BB275	1	Dec 15, 2010	Beech 200	Installation of L-3 Communications Skywatch HP Model SKY899 (TCAS I)	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number b) Registration c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA10-262/D b) C-GASW c) U39	1	2010-12-15	Hawker Beechcraft 99	Installation of Mid-Continent MD4300-411 Standby Attitude Indicator	-	-
a) C-LSA10-264/D b) C-FCGU, C-GXHF c) BB301, BB1343	1	2010-12-17	Hawker Beechcraft 200, B200	Installation of Mid-Continent 4300-411 Standby Attitude Indicator on Copilot's Side	-	-
a) C-LSA10-265/D b) C-FKHD, C-FVCE c) U11, U118	1	2010-12-18	Hawker Beechcraft 99, 99A	Installation of Mid-Continent 4200-10 Standby Attitude Indicator with MD420 Emergency Power Supply.	-	-
a) C-LSA11-010/D b) C-GQNJ c) BB275	1	Feb 07, 2011	Beech 200	Deviations to FAA STC SA01933LA-D to include an alternate HSI, autopilot, and interface to DAC GDC-31	-	-
a) C-LSA11-069/D b) C-GMFY c) 2078	1	Apr 20, 2011	Bombardier CL-215-1A10	Installation of ISAT-100 with GPS/Iridium antenna	-	-
a) C-LSA11-096/D b) C-GSKB c) 99	1	Apr 18, 2011	DHC-6-100	MVP-50T Engine display System		
a) C-LSA11-117/D b) C-FTMU, C-FTSU, C-FTWU c) 782, 451, 371	1	May 24, 2011	DHC-6-300	Engine Chip Detector	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA11-144/D b) C-GWUY c) BB-77	1	Jul 25, 2011	Beech B200	Installation of Mid-Continent 4200-10 Standby Attitude Indicator with MD-420 Emergency Power Supply	-	-
a) C-LSA11-170/D b) TC-TKH, TC-TKT c) 1104, 1097	1	Oct 28, 2011	CL-215-1A10	Installation of Max-Viz EVS-1500 Enhanced Vision System with Two Displays	-	-
a) C-LSA12-092/D b) c)	1	Oct 17, 2012	Cessna 208	Installation of Appareo Vision 1000	-	-
a) C-LSA12-114/D b) C-GCPY, C-GUAT c) 101, 10	1 2	July 25, 2012 Oct 22, 2012	DHC-7-102 DHC-7-103	Avionics Upgrades	-	-
a) C-LSA12-172/D b) VP-FAZ c) 748	1	Sep 28, 2012	DHC-6-300	Scientific Probe Installation (Brechtel Aerosol Probe and Cloud Droplet Probe)	-	-
a) C-LSA12-203/D b) C-FCGU, C-GNHM, C-GTUC, C-GBYN c) BB301, BB188, BB268, BB1232	1	Nov 09, 2012	Beech 200, B200	Deviations to FAA STC SA01340LA for Installation of Sandel ST3400 TAWS/RMI, Class B	-	-
a) C-LSA13-039/D b) All 4 x BAS c)	1	Feb 20, 2013	DHC-6-300	Electrical System Upgrade to 250 Amps	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA13-078/D b) C-GDPB c) BL-44	1	Jul 15, 2013	Beech B200C	Deviations to FAA STC SA01933LA-D to Install GPS-400W	-	-
a) C-LSA05-198/D b) VP-FBL/VP-FBB/VP-FBC/VP-FAZ c) 839/ 783/ 787/ 748	2	2007-07-20	DHC-6-300	Installation of LITEF GmbH LCR-92S Attitude and Heading Reference System (AHRS) into DHC-6-300		
a) C-LSA01-610/D b) c)	1	2001-04-30	Pilatus PC6	Gross Weight Increase		
a) C-LSA01-630/D b) C-GAAP c) 569	1	2001-06-29	Pilatus PC6	Installation of Wipaire Model 6100 Seaplane Floats	-	-
a) C-LSA02-631/D - A14CE b) C-FQCN/N918BB c) U-126 / U-118	1	2002-07-19	Beech 99, 99A	Radio Altimeter Antennas Installation	-	-
a) C-LSA03-271/D b) VP-FAZ c) 748	1	2003-07-16	DHC-6-300	Electrical Conduit Installation	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA04-177/D b) C-FVCE c) U118	1	2004-07-27	Raytheon 99A	Installation of Single Garmin GNS-430 GPS/Nav/Comm System	-	-
a) C-LSA04-357/D b) C-GZUZ c) B143	1	2004-10-20	Raytheon A100	Installation of a L-3 Communications - Aviation Recorders (Fairchild) A100S Cockpit Voice Recorder system	-	-
a) C-LSA06-110/D b) C-FGPC c) BL-13	1	2006-07-12	Raytheon 200C	Installation of a GPS Antenna for a FreeFlight system on Raytheon 200C s/n BL-13. Scope includes antenna installation and structural aspects but excludes antenna lead installation, integration with avionics, and electrical power.	-	-
a) C-LSA06-383/D b) C-FBLY c) 244	1 2	2006-12-21 2007-03-16	DHC-6-300	Installation of Supplemental Oxygen System	-	-
a) C-LSA07-095/D b) C-FMRU c) 788	1	2007-03-30	DHC-6-300	Installation of Flight Crew Supplemental Oxygen System	-	-
a) C-LSA07-198/D b) CFLXP/CFNBI/CFNBL/CFOIM/CFOIJ/N206EA/N321EA c) 217/454/625/467/756/194/299	1	2007-06-27	DHC-6 200, 300	Installation of an avionics shelf in tail of a DHC-6 Aircraft.	-	-

<i>Transport Canada</i>			<i>Aircraft Type</i>	<i>Description</i>	<i>FAA Approval</i>	<i>EASA (JAA) Approval</i>
<i>a) Approval Number</i> <i>b) Registration</i> <i>c) Serial No</i>	<i>Issue</i>	<i>Issue Date</i>				
a) C-LSA99-617/D b) c)	1	1999-04-27	DHC-6 Series 300	Ferry Fuel System		
a) W-LSA91-071 b) C-FMEB c) 242094	1	1991-06-07	Piper PA-24	Installation of ACK A30 BLIND Altitude Encoder and AT50A Transponder.		
a) W-LSA91-072 b) FVSJ c)U206B-0819	1	1991-06-05	Cessna U206B	ACK A30 Encoder Installation.		
a) W-LSA91-073 b) FTTJ c) 158E-1085	1	1991-08-06	Cessna A185E	Blind Altitude Encoder Installation.		
a) W-LSA91-076 b) C-GIHE c)28-7225443	1	1991-08-07	Piper PA-28- 140	Blind Altitude Encoder Installation.		
a) W-LSA97-108/D b) c)	1	1997-05-09	DHC-6-300	CVR Installation	??	
a) W-LSA98-028/D b) c)	1	1998-04-20	Beech B100	Landing Gear Retraction Motor/Transmission Support Brackets Modification	??	