



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
RDC						
C-RA16-049/D Issue 1 Apr 25, 2016	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320, -400	Lug Repair, Cockpit Seat Pedestal, PN C3FF20-5	None	None
C-RA13-166/D Issue 1 Oct 25, 2013	-	-	DHC-6-100, -200, -300	Repair Horizontal Stabilizer Skin	None	None
C-RA08-055/D Issue 3 Feb 7, 2014	-	-	DHC-6-100, -200, -300	Repair of Bleed Air Ducts	None	None
C-RA07-396/D Issue 1 Dec 31, 2007	-	-	DHC-6-100, -200, -300	Repair of Elevator End Rib P/N C6TE1026-27 and C6TE1026-29	None	None
C-RA06-255/D Issue 1 Aug 11, 2006	-	-	DHC-6-100, -200, -300	Generator cooling duct assembly repair	None	None
C-RA06-254/D Issue 1 Aug 11, 2006	-	-	DHC-6-100, -200, -300	Control surface tip weld repair	None	None
C-RA04-386/D Issue 1 Nov 19, 2004	-	-	DHC-6-100, -200, -300	Replacement of aluminum power wires between the generator relay and the left and right firewalls	None	None
C-RA03-418/D Issue 1 Dec 1, 2003	-	-	DHC-6-100, -200, -300	Repair of LH & RH Wing Flap Hinge Arm	None	None
C-RA03-080/D Issue 1 Jul 16, 2003	-	-	DHC-6-100, -200, -300	Jack Pad Repair	None	None
C-RA03-079/D Issue 1 Aug 29, 2003	-	-	DHC-6-100, -200, -300	Bracket Assembly Repair	None	None
C-RA03-078/D Issue 1 Aug 22, 2003	-	-	DHC-6-100, -200, -300	Fuel Tube Repair	None	None
C-RA02-607/D Issue 1 Jan 31, 2002	-	-	DHC-6-300 (C-GHBP / 380)	Over-sized Fasteners on Upper Main Frame Splice	None	None
C-RA01-644/D Issue 1 Aug 3, 2001	-	-	DHC-6-300 (N204SA / 402)	Over-sized Fasteners on Main Frame Splice	None	None
C-RA01-163 Issue 1 Nov 15, 2001	-	-	DHC-6-100, -200, -300	Trim Cable Pulley Bracket Repair	None	None
C-RA01-003/D Issue 1 Jan 18, 2001	-	-	Beechcraft Kingair 100 (C-GXVX / B-18)	Main Spar Repair at Left Wings F.S. 78.0	None	None
C-RA93-054/D Issue 1 Apr 14, 1993	-	-	BRITTEN NORMAN BN2A 26 (C-GZGO / 2017)	Fuselage Repair	None	None
C-RA92-018/D Issue 1 Jan 28, 1992	-	-	BEECH 60 (Duke) (C-FBQC)	Loran Antenna Support Repair	None	None
C-RA92-017/D Issue 2 May 1, 1992	-	-	DHC-6-300 (C-FMYV / 374)	Sta 111.0 Skin Joint Repair	None	None



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
W-RA97-139 Issue 2 Jan 21, 2000	-	-	DHC-6-100, -200, -300	Fore Flap Hinge Arm Repair	None	None
W-RA97-039/D Issue 1 May 16, 1997	-	-	DHC-6-300 (C-GQKZ / 532)	Wing Repair	None	None
W-RA95-034/D Issue 3 Mar 20, 1996	-	-	DHC-6-300 (C-FTJJ / 325)	Wing Assembly Repair	None	MMS946001 Rev - Sep 15, 1995
PDA						
PDA18-10 Issue 1 May 22, 2018	-	-	DHC- 6-100, -110, -200, -210, - 300, -310, -320, -400	Fuel Cell Sump Plate Assemblies	None	None
PDA16-11 Issue 1 Aug 3, 2016	-	-	DHC-6-100, -110, -200, -210, - 300, -310, -320, -400	Replacement Cabin Floor Rails	None	None
PDA15-14 Issue 1 Aug 7, 2015	-	-	DHC- 6-100, -200, -300	Replacement Engine Harness	None	None
PDA15-10 Issue 1 Jul 16, 2015	-	-	DHC- 6-100, -200, -300	Replacement De-Icing Timer	None	None
PDA13-4 Issue 3 Aug 4, 2017	-	-	DHC-6-100, -110, -200, -210, - 300, -310, -320, -400	Replacement, Air Conditioning, Heating and Cooling Ducts	None	None
PDA07-11 Issue 3 Oct 15, 2013	-	-	DHC-6-100, -200, -300, -400	D-Nose Door Assembly	None	None
PDA02-19 Issue 1 Aug 20, 2002	-	-	DHC-6-100, -200, -300	TCCA-PDA-RMA-976101-11, Upper Fuselage Skin Panel (Aft)	None	None
PDA02-3 Issue 1 Aug 20, 2002	-	-	DHC-6-100, -200, -300	TCCA-PDA-RMA-330207-1, Upper Fuselage Skin Panel (Forward)	None	None
LSTC						
C-LSA18-024/D Issue 2 May 16, 2018	-	-	DHC-6-300 (680)	Installation, Research Provisions	None	E121231 Rev - Feb 26, 2018
						E121331 Rev A Apr 6, 2018
						E121831 Rev - Apr 6, 2018
C-LSA17-109/D Issue 1 Sep 27, 2017	-	-	DHC-6-300 (687, 729, 783)	Installation, Fuselage Plug for Airstair Doors, Enlarged Cargo Door Aircraft	None	Viking Air Ltd Maintenance Documents
C-LSA16-124/D Issue 1 Nov 8, 2016	-	-	Textron Aviation A185F	Installation of Modified Aft Passenger Seat Frame	None	None
C-LSA16-029/D Issue 1 Mar 4, 2016	-	-	Beech B99 (C-FWIK / U-39)	De-activation, Janitrol Heater	None	E115931 Rev A Mar 2, 2016
C-LSA14-200/D Issue 1 Dec 12, 2014	-	-	DHC-6-300 (VP-FAZ / 748, VP- FBB / 783, VP-FBC / 787, VP-FBL / 839)	Installation of Zeiss NT2 Drift Sight	E110430 Rev - Nov 27, 2014	E110431 Rev - Nov 27, 2014



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA14-053/D Issue 1 Mar 27, 2014	-	-	Hawker Beechcraft A100 (C-GVMI / B222)	Chelton AIU-2 Interface to S-Tec System 65 Autopilot	E109830 Rev - Mar 27, 2014	150-045055 Rev L Sep 6, 2011
C-LSA14-040/D Issue 1 Mar 26, 2014	-	-	Hawker Beechcraft A100 (C-GVMI / B222)	Installation of Mid-Continent Instruments MD302 Standby Attitude Module (SAM)	E110630 Rev - Mar 20, 2014	E110631 Rev - Feb 1, 2014
C-LSA13-165/D Issue 2 Jan 29, 2016	-	-	Bombardier CL-215-6B11 (C-FIGJ / 2084, C-FNJC / 2077, C-FOFI / 2081, C-GMFW / 2082, C-GMFX / 2083, C-GMFY / 2078, C-GMFZ / 2086, C-FDNL / 2091, C-FYWK / 2094)	Artex C406-N ELT with Programming Adapter Installation	None	E109531 Rev - Nov 1, 2013
C-LSA13-157/D Issue 1 Oct 15, 2013	-	-	DHC-6-300 (VP-FAZ / 748, VP-FBB / 783, VP-FBC / 787, VP-FBL / 839)	Installation, Lower Fuselage Cutouts between FS 347 and 362	None	PSM 1-6-3 PSM 1-6-7
C-LSA13-149/D Issue 1 Oct 10, 2013	-	-	DHC-7-102, -103 (C-GCPY / 101, C-GFFL / 074, C-FWZV / 81, C-GCEV / 63, C-GUAT / 10)	Switch installation to enable the Start Pac Model 3328 Special Ground Power Unit (GPU) to provide external DC power	None	PSM 1-7-2
C-LSA13-147/D Issue 1 Nov 8, 2013	-	-	DHC-6-300 (VP-FAZ / 748, VP-FBB / 783, VP-FBC / 787, VP-FBL / 839)	Installation of Launch Tube in Existing Fuselage Cut-out	None	E109431 Rev A Nov 19, 2013
C-LSA13-078/D Issue 1 Jul 15, 2013	-	-	Hawker Beechcraft B200C (C-GDPB / BL44)	Deviations to STC SA01933LA-D to install Garmin GPS-400W	E108430 Rev - Jul 15, 2013	190-00356-65 Rev C Feb 28, 2013
C-LSA13-039/D Issue 1 Feb 20, 2013	-	-	DHC-6-300 (VP-FAZ / 748, VP-FBB / 783, VP-FBC / 787, VP-FBL / 839)	Electrical System Upgrade to 250 Amps	E107830 Rev - Feb 12, 2013	PSM 1-63-2
C-LSA12-203/D Issue 1 Nov 9, 2012	-	-	Hawker Beechcraft 200, B200 (C-FCGU / BB301, C-GNHM / BB188, C-GTUC / BB268, C-GBYN / BB1232)	Deviations to STC SA01340LA for Installation of Sandel ST3400 TAWS/RMI, Class B	E107330 Rev - Nov 9, 2012	E107331 Rev - Oct 26, 2012
C-LSA12-172/D Issue 1 Sep 28, 2012	-	-	DHC-6 300 (VP-FAZ / 748)	Installation of Aerosol Inlet Probe or Cloud Droplet Probes	E106030 Rev - Sep 28, 2012	E106031 Rev - May 1, 2012
C-LSA12-114/D Issue 2 Oct 22, 2012	-	-	DHC-7-102, -103 (C-GCPY / 101, C-GUAT / 10)	Avionics upgrade to include KLN-900, MFRD, MKVI EGPWS, and Standby Attitude Indicator	E106330 Rev - Sep 28, 2012	E106331 Rev - May 1, 2012
					E106425 Rev A Aug 30, 2012	E106426 Rev A Aug 29, 2012
					E106435 Rev A Aug 30, 2012	E106436 Rev A Aug 29, 2012
					E106445 Rev A Aug 30, 2012	E106446 Rev A Aug 29, 2012
					E106455 Rev A Aug 30, 2012	E106456 Rev A Aug 29, 2012
C-LSA12-092/D Issue 1 Oct 17, 2012	-	-	Cessna 208, 208B (C-GATY / 20800305, C-FKAY / 208B0470, C-FSKS / 208B0722, C-GATH / 208B1244)	Installation of Appareo Vision 1000 System	None	E105631 Rev - Apr 27, 2012
C-LSA11-170/D Issue 1 Oct 28, 2011	-	-	Bombardier CL-215-1A10 (TC-TKH / 1104, TC-TKT / 1097)	Installation of Max-Viz EVS-1500 Enhanced Vision System with Two Displays	E104430 Rev - Oct 18, 2011	E104431 Rev - Jul 5, 2011



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA11-144/D Issue 2 Apr 18, 2017	-	-	Hawker Beechcraft B200 (C-GWUY / BB77, C-GACA / BB1309)	Installation of Mid-Continent 4200-10 Standby Attitude Indicator with MD-420 Emergency Power Supply	E103430 Rev A Mar 15, 2017	E103431 Rev - Apr 19, 2011
C-LSA11-117/D Issue 1 May 24, 2011	-	-	DHC-6-300 (C-FTMU / 782, C-FTSU / 451, C-FTWU / 372)	Engine Chip Detector	E103330 Rev - May 24, 2011	E103331 Rev - Apr 8, 2011
C-LSA11-096/D Issue 1 Apr 18, 2011	-	-	DHC-6-100 (C-GSKB / 99)	MVP-50T Engine Display System	E101530 Rev - Feb 9, 2012 E103230 Rev - Apr 18, 2011	E101531 Rev - Oct 12, 2010
C-LSA11-069/D Issue 4 Mar 14, 2014	-	-	Bombardier CL-215-1A10, CL-215-6B11 (C-GMFW / 2082, C-GMFX / 2083, C-GMFY / 2078, C-GMFZ / 2086, C-GBOW / 1087, C-GMAK / 1107)	Installation of ISAT-100 with GPS/ Irdium antenna	None	E102831 Rev A Feb 22, 2013 E106131 Rev - Nov 14, 2013
C-LSA11-010/D Issue 1 Feb 7, 2011	-	-	Hawker Beechcraft 200 (C-GQNJ / BB275)	Deviations to STC SA01933LA-D to include an alternate HSI, autopilot, and interface to DAC GDC-31	E102030 Rev - Feb 7, 2011	190-00357-65 Rev B Jul 30, 2009
C-LSA10-265/D Issue 1 Dec 18, 2010	-	-	Hawker Beechcraft 99, 99A (C-FKHD / U11, C-FVCE / U118)	Installation of Mid-Continent 4200-10 Standby Attitude Indicator with MD420 Emergency Power Supply	E102430 Rev - Dec 17, 2010	E102431 Rev - Nov 17, 2010
C-LSA10-264/D Issue 2 Sep 15, 2016	-	-	Hawker Beechcraft 200, B200 (C-FCGU / BB301, C-GXHF / BB1343, C-FAKN / BB216)	Installation of Mid-Continent 4300-411 Standby Attitude Indicator on Co-pilot's side	E102630 Rev - Dec 16, 2010	E102631 Rev - Dec 7, 2010
C-LSA10-262/D Issue 1 Dec 15, 2010	-	-	Hawker Beechcraft 99 (C-GASW / U39)	Installation of Mid-Continent MD4300-411 Standby Attitude Indicator	E102330 Rev - Dec 15, 2010	E102331 Rev - Nov 16, 2010
C-LSA10-251/D Issue 1 Dec 15, 2010	-	-	Hawker Beechcraft 200 (C-FKJI / BB105, C-GJLI / BB347, C-GQNJ / BB275)	Installation Of L-3 Communications Skywatch HP MODEL SKY899 (TCAS 1)	E101930 Rev - Dec 14, 2010	E101931 Rev - Oct 12, 2010
C-LSA10-250/D Issue 1 Dec 10, 2010	-	-	Aero Commander 500-S (C-GKEE / 3308)	Installation Of Avidyne EXP-5000 PFD	E101830 Rev - Dec 7, 2010	E101831 Rev - Oct 12, 2010
C-LSA10-213/D Issue 1 Oct 19, 2010	-	-	Hawker Beechcraft 200C (C-GCVS / BL13)	Deviations To STC To Install Garmin GPS-400W	E101730 Rev - Oct 19, 2010	190-00356-65 Rev C Feb 28, 2013
C-LSA10-192/D Issue 1 Sep 8, 2010	-	-	British Aerospace BAE 146-200 (C-GCUP / E2096)	Installation Of Dual Honeywell GNS-XLS FMS	146-3461-01-1012 Rev IR Sep 8, 2010	146-3461-01-0002 Rev IR May 10, 2010
C-LSA10-083/D Issue 1 May 25, 2010	-	-	Raytheon C90A (C-FHLL / LJ1111)	Installation of Universal Avionics CVR-30B	None	E100831 Rev - Apr 19, 2010
C-LSA10-066/D Issue 1 Apr 6, 2010	-	-	Beech C90 (C-GTWW / LJ657)	Installation of Sandel ST3400 TAWS/RMI, Class B	E100630 Rev - Apr 1, 2010	E100631 Rev - Mar 18, 2010
C-LSA10-065/D Issue 1 Apr 6, 2010	-	-	Beech C90 (C-GTWW / LJ657), Raytheon C90A (C-FHLL / LJ1111)	For S/N LJ-657: Deviations to STC SA01552CH-D for the installation of L-3 Communications Skywatch HP TCAS 1 System, Model SKY899/ For S/N LJ-1111: Upgrade existing SKY497 to SKY899	E100530 Rev - Apr 7, 2010	ES90-210999-200 Rev IR Nov 14, 2001



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA10-061/D Issue 1 Apr 28, 2010	-	-	Bombardier CL215-1A10 (C-GMAF / 1044)	Relocation Of ADF-60B Antenna	None	218431 Rev - Sep 8, 2009
C-LSA09-260/D Issue 1 Nov 10, 2009	-	-	Bombardier CL215-1A10 (C-FTUV / 1020, C-FTXI / 1016, C-GMAF / 1044, C-GUMW / 1065)	Installation of: Dual Collins VIR-32 VHF NAV systems/ VHF-22A Comm systems/ ADF-60B ADF systems, Collins DME-42 DME system/ TDR-94 Transponder system, Dual NAT N301A-000 Audio system, NAT NTX-138 FM system, SKYTRAC ISAT-100 Satcom system, Pilot & Co-pilot Collins RMI-36 indicators, Artex C4-6N ELT	None	218431 Rev - Sep 8, 2009
C-LSA09-069/D Issue 1 Mar 23, 2009	-	-	Bombardier CL215-1A10 (C-FTUV / 1020, C-FTXI / 1016, C-GMAF / 1044, C-GUMW / 1065)	Sandel SN4500 EHSI Installation	217630 Rev - Mar 30, 2009	217631 Rev - Mar 4, 2009
C-LSA09-068/D Issue 2 June 28, 2018	-	-	Bombardier CL215-1A10 (1068, 1087, 1107, 1016, 1020, 1044, 1065)	Garmin GPS 400W With SHADIN ADC-2000 & Garmin GDL-69 Installation	217530 Rev A Apr 16, 2009	217531 Rev - Mar 4, 2009
C-LSA09-048/D Issue 4 Jan 9, 2018	-	-	Beech 1900D (UE128, UE58, UE334, UE5, UE8, UE268, UE332, UE333)	Toilet installation	None	None
C-LSA07-260/D Issue 1 Oct 10, 2007	-	-	DHC-6-300 (C-FOPJ / 243, C-FOPJ / 344, C-FOPG / 232)	Installation of a Sandel SA4550 Primary Attitude Display	210730 Rev - Oct 9, 2007	210731 Rev - Sep 18, 2007
C-LSA07-198/D Issue 1 Jun 27, 2007	-	-	DHC-6-200, -300	Installation Of An Avionics Shelf in Tail	None	None
C-LSA07-095/D Issue 1 Mar 30, 2007	-	-	DHC-6-300 (C-FMRU / 788)	Installation Of Flight Crew Supplemental Oxygen System	FMS-1177-03 Rev 1 Mar 16, 2007	MMS-1177-01 Rev 2 Oct 7, 2008
C-LSA07-029/D Issue 3 May 5, 2009	-	-	Bombardier CL215-1A10 (C-FTUV / 1020, C-FTXI / 1016, C-GMAF / 1044, C-GMAK / 1107, C-GUMW / 1065)	Installation of L-3 Sky Watch HP (TCAS I) system and a EVS Technology Max Viz EVS-1000 Enhanced Vision System	210830 Rev - Mar 26, 2007 210930 Rev B Jun 3, 2008	210831 Rev B Jun 3, 2008
C-LSA06-383/D Issue 2 Mar 16, 2007	-	-	DHC-6-300 (C-FBLY / 244)	Installation Of Supplemental Oxygen System	FMS-1177-02 Rev 1 Feb 21, 2007	MMS-1177-01 Rev 2 Oct 7, 2008
C-LSA05-360/D Issue 1 Nov 1, 2005	-	-	DHC-6-300 (N48RF / 740)	Nose Boom Installation	FMS386401 Rev IR Nov 1, 2005	MMS386401 Oct 1, 2005
C-LSA05-234/D Issue 1 Aug 25, 2005	-	-	DHC-6-300 (VP-FAZ / 748)	Masin Installation	FMS370201 Rev 1 Aug 5, 2005	MMS370201 Rev 1 Apr 8, 2005
C-LSA05-200/D Issue 1 Nov 23, 2005	-	-	DHC-6-300 (C-FWAH)	IHAS 8000 Integrated Hazard Awareness System Installation	199230 Rev - Nov 22, 2005	199231 Rev - Oct 5, 2005
C-LSA05-132/D Issue 5 Nov 3, 2016	-	-	DHC-6-100, -200 (C-FASQ / 78, N97DZ / 97, C-FPOK / 116, N206EH / 194, N901ST / 208)	Hartzell HC-B3TN-3D(Y) Propeller Installation	FMS379501 Rev 4 Oct 21, 2016	MMS379501 Rev 4 Sep 26, 2016
C-LSA04-357/D Issue 1 Oct 20, 2004	-	-	Raytheon (Beech A100 (C-GZUZ / B-143)	Installation of a L-3 Communications - Aviation Recorders (FAIRCHILD) A100S Cockpit Voice Recorder System	None	195431 Rev - Oct 19, 2004
C-LSA04-177/D Issue 1 Jul 27, 2004	-	-	Raytheon 99A (C-FVCE / U118)	Installation of Single Garmin GNS-430 GPS/NAV/COMM System	194530 Rev - Jun 30, 2004	194131 Rev - Jul 1, 2004



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA03-271/D Issue 1 Jul 16, 2003	-	-	DHC-6-300 (VP-FAZ / 748)	Electrical Conduit Installation	None	None
C-LSA03-137/D Issue 1 Dec 31, 2003	-	-	DHC-6-300 (C-FTXQ / 308)	Single GNS 430 GPS / NAV / COMM System Installation	94839-801 Rev - Oct 20, 2003	94839-701 Rev - Oct 20, 2003
C-LSA02-631/D Issue 1 Jul 19, 2002	-	-	Raytheon (Beech) 99, 99A (C-FQCN / U-126, N918BB / U-118)	Radio Altimeter Antennas Installation	None	None
C-LSA01-652/D Issue 1 Sep 14, 2001	-	-	DHC-6-300 (D-GJDE / 471)	Installation of Universal CVR-30B Cockpit Voice Recorder	None	None
C-LSA01-646/D Issue 1 Sep 21, 2001	-	-	DHC-6-300 (C-GBEB / 272)	Installation of Universal CVR-30B Cockpit Voice Recorder	None	None
C-LSA01-645/D Issue 1 Aug 14, 2001	-	-	DHC-6-300 (C-GBEB / 272)	Elevator Trailing Edge Replacement	None	None
C-LSA01-636/D Issue 1 Aug 8, 2001	-	-	DHC-6-300 (C-GHBP / 380)	Fastener Replacement on the R/H Wing Spar	None	None
C-LSA01-630/D Issue 1 Jun 29, 2001	-	-	Pilatus PC-6/B-H2 (C-GAAP / 569)	Installation of Wipaire Model 6100 Seaplane Floats	Approved Manual Supplement of the Pilatus PC-6/ B2-H4 at a Gross Weight of 6100 Pounds with Wipline Model 6100 Floats Jul 14, 1994	None
C-LSA01-610/D Issue 1 Apr 30, 2001	-	-	Pilatus PC-6/B-H2 (C-GAAP / 569)	Gross Weight Increase	1072-20 Rev 3 May 1992	01975
C-LSA00-233/D Issue 2 Dec 5, 2000	-	-	Beechcraft Kingair 100 (C-GXVX / B18)	Installation of Dual Garmin GNS 430 NAV / COMM / GPS (IFR GPS Enroute, Terminal, Approach)	C73590 Rev N/C	None
C-LSA00-207/D Issue 1 Jun 29, 2000	-	-	Neech 100 (C-GXVX / B18)	Installation of GA-56 GPS Antennas, FS 153.3, FS 170.7 (Structural Provisions Only)	None	None
C-LSA00-174/D Issue 1 May 15, 2000	-	-	DHC-6-300 (C-FWUL / 360)	Removal Of Auxiliary Battery	None	None
C-LSA99-617/D Issue 1 Apr 27, 1999	-	-	DHC-6-300 (C-GCGW)	Ferry Fuel System		
C-LSA94-246 Issue 2 Dec 20, 1994	-	-	DHC-6-200 (V3-HTA / 112)	Installation of Pratt & Whitney PT6A-27 ENGINES	A61290 Rev A Dec 20, 1994	None
C-LSA93-130/D Issue 1 Sep 30, 1993	-	-	DHC-6-100 (C-FAWC / 108)	Baggage Door Installation	None	None
C-LSA93-041/D Issue 1 Mar 24, 1993	-	-	DHC-6-200, -210 (GKNR / 186, FJCL / 151)	CVR Installation (Structures)	None	None



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
W-LSA98-124/D Issue 1 Dec 20, 1998	-	-	Beechcraft Model 99 (C-FVCE / U-118, C-GAWW / U-137, C-GAVV / U-142)	Installation of PHOENIX VR-1010-24-2B Voltage Regulators	None	None
W-LSA98-123/D Issue Dec 20, 1998	-	-	Beechcraft Model 99 (C-FQCN / U-126, C-FOZU / U-130)	Installation of PHOENIX VR-1010-24-2B Voltage Regulators	None	None
W-LSA98-028/D Issue 1 Apr 20, 1998	-	-	Beech B100 (C-FQOV)	Landing Gear Retraction Motor/ Transmission Support Brackets Modification		
W-LSA97-150/D Issue 1 Feb 1, 1998	-	-	DHC-6-300 (C-GBEB / 272)	Ferry Fuel System	FMS986301 Rev 1 Jan 29, 1998	None
W-LSA97-144/D Issue 1 Dec 12, 1997	-	-	Beech 99A (C-GAWW / U-137, C-GAVV / U-142, C-GAVU / U-143)	Aft Avionics Rack Installation	None	None
W-LSA97-130/D Issue 1 Dec 4, 1997	-	-	Beech 99A (C-GAWW / U-137, C-GAVV / U-142, C-GAVU / U-143)	Radio Altimeter Antennas Installation	None	None
W-LSA97-108/D Issue 1 May 9, 1997	-	-	DHC-6-300 (C-GQKZ / 532)	Twin Otter CVR Installation	None	None
W-LSA97-026/D Issue 1 Mar 17, 1997	-	-	DHC-6-300 (C-GBGC / 701)	Replacement Fuselage Skin Panel	None	None
W-LSA95-079 Issue 1 Sep 21, 1995	-	-	DHC-6-300 (C-FMOL / 303)	Installation of a Garmin GPS 165 Global Positioning System	None	None
C-LSA95-241 Issue 2 Jun 6, 1996	-	-	DHC-6-200 (N10EA / 199, N30EA / 198)	Installation of Pratt & Whitney PT6A-27 ENGINES	None	None
W-LSA93-133 Issue 1 Dec 17, 1993	-	-	Beechcraft King Air 100 (C-FQOV / B-38)	Installation of a Trimble TNL-2000T GPS Receiver and ETS 802100-29 CDI	Dec 17, 1993	None
W-LSA92-129 Issue 1 Aug 10, 1992	-	-	DHC-6-300 (C-FMYV / 374)	Avionics installation including Radio Master, Directional Gyro, and Audio Panel	22272-801 Rev - Aug 10, 1992	None
W-LSA92-108 Issue 1 Jun 12, 1992	-	-	DHC-6 (C-FISO / 204)	Installation of HF and Compass System	None	None
W-LSA92-06 Issue 2 Jan 17, 1992	-	-	DHC-6-300 (C-FKKV / 371)	King KT7A Transponder and ACK-A30 Encoder	None	None
W-LSA91-95 Issue 1 Jul 19, 1991	-	-	DHC-6-300 (C-FIZD / 461)	Avionics Refit	None	None
W-LSA91-076 Issue 1 Aug 7, 1991	-	-	Piper PA28 140 (C-GIHE / 28-7225443)	Blind Altitude Encoder Installation	None	None
W-LSA91-073 Issue 1 Aug 6, 1991	-	-	Cessna A185E (C-FTTJ / 185E-1085)	Blind Altitude Encoder Installation	None	None
W-LSA91-072 Issue 1 Jun 5, 1991	-	-	Cessna U206B (C-FVSJ / U206B-0819)	ACK A30 Encoder Installation	None	None



129 MacLaurin Drive
 Springbank Airport
 Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
W-LSA91-071 Issue 1 Jun 7, 1991	-	-	Piper PA-24 (C-FMEB / 242094)	Installation of ACK A30 Blind Altitude Encoder and AT50A Transponder	None	None