

# Replacement De-Ice Timer

Rocky Mountain Aircraft has recently been granted PDA15-10, and a revision to our Manufacturing Limitations by Transport Canada to produce P/N RMA-42E13-3A/3B



- Solid State, not Transistorized
- Tested to RTCA/DO-160G Standard
- MTBF 25,000 HRS (Est)

This is a “plug and play” replacement for the Bendix Transistorized Timer originally supplied with your legacy series Twin Otter. No rewiring or remounting is required, simply remove the original unit, mount the replacement in the same place, and plug in!