



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
STC						
SA18-51 Issue 1 Apr 26, 2018	-	-	DHC-6-1, -100, -110, -200, -210, -300, -310, -320, -400	Installation, Rudder Improvement	None	E121531 Rev - Jan 30, 2018
SA17-81 Issue 1 Aug 15, 2017	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320	Installation of LED Replacement Cockpit Panels	None	E115899 Rev - Aug 4, 2017
SA17-78 Issue 2 Feb 5, 2018	SA040033NY Jan 2, 2018	-	DHC-6-100, -110, -200, -210, -300, -310, -320	Replacement, LED Master Caution Panel	E108530 Rev - Aug 15, 2017	E108531 Rev B Aug 9, 2017 E108532 Rev B Aug 9, 2017
SA17-29 Issue 1 Apr 10, 2017	SA03926NY Jun 9, 2017	-	DHC-6-400	Fold Up Utility Seats	None	E114231 Rev - Apr 7, 2017 E114230 Rev A Jan 7, 2019 E114232 Rev A Jan 25, 2019
SA16-45 Issue 1 Apr 12, 2016	SA03757NY Jul 15, 2016	-	DHC-6-100, -110, -200, -210, -300, -310, -320, -400	Installation of Replacement Fuel Manifold Tubes	None	None
SA15-49 Issue 1 Jul 9, 2015	-	-	DHC-6-100, -200, -300	Radar Altimeter Mounts (Structural Provisions Only)	None	None
SA15-44 Issue 1 May 28, 2015	SA03868NY Feb 21, 2017	10059728 Oct 11, 2016	DHC-6-100, -200, -300	Fuel Quantity Indication System Replacement	None	E110331 Rev B Jul 10, 2017 E110332 Rev A Mar 29, 2016
SA14-61 Issue 2 Feb 6, 2017	-	-	DHC-6-100, -200, -300	Installation of Dual LCR-100 Attitude Heading Reference System (AHRS)	E110940 Rev A Feb 3, 2017 E110930 Rev A Feb 3, 2017	E110941 Rev A Feb 1, 2017 E110931 Rev A Feb 1, 2017
SA13-38 Issue 1 Jun 5, 2013	SA03363NY Feb 27, 2014	-	DHC-6-100, -200, -300	Installation of Universal Avionics TAWS, Class A	E108030 Rev - Jun 4, 2013	E108031 Rev A Jan 7, 2014
SA13-37 Issue 1 Jun 19, 2013	-	-	DHC-6-100, -200, -300	Installation of Universal Avionics EFI-890R PFD	E103530 Rev B Mar 1, 2017	E103531 Rev C May 23, 2017
SA13-27 Issue 1 Aug 27, 2013	-	-	DHC-6-1, -100, -110, -200, -210, -300, -310, -320, -400	Barrier Net Installation	293490 Rev A Aug 27, 2013	293430 Rev B Nov 13, 2013



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
SA12-13 Issue 2 Dec 23, 2015	-	10047440 Dec 12, 2013	DHC-6-100, -200, -300	Installation of Electronics International MVP-50T Engine Dispal System	E101530 Rev C Aug 15, 2017	E101531 Rev A May 10, 2012 (SA12-13 Issue 1 only)
						E111531 Rev A Sep 22, 2017
						E111532 Rev - Dec 15, 2015
SA11-80 Issue 1 Nov 14, 2011	SA03150NY Oct 3, 2012	10040247 Jun 19, 2012	DHC-6-100, -200, -300	Installation of either Universal Avionics CVR-120A or CVR-120R Cockpit Voice Recorder	None	E103131 Rev B Aug 8, 2012
SA11-79 Issue 1 Oct 12, 2011	SA03346NY Nov 22, 2013	10038966 Mar 27, 2012	DHC-6-100, -200, -300	Installation of Dual or Single Garmin GTN-650 or GTN-750 GPS/NAV/COMM	E102930 Rev A Dec 1, 2016	E102931 Rev B Nov 25, 2016 E102932 Rev - Nov 25, 2016
SA11-72 Issue 1 Aug 23, 2011	-	10037908 Jan 5, 2012	DHC-6-100, -200, -300	Installation of Engine Chip Detectors	E104630 Rev A May 2, 2016	E104631 Rev A Feb 10, 2016
SA10-24 Issue 3 May 21, 2013	SA03357NY Dec 12, 2013	-	DHC-6-100, -200, -300	Installation of L-3 Communications ESI-1000 Electronic Standby Indicator, or L-3 Communications GH-3900.2 Electronic Standby Instrument System (ESIS), or Mid-Continent Instruments 4200-10 Standby Attitude Indicator, or Mid-Continent Instruments 4300-411 Standby Attitude Indicator	E100130 Rev - Jun 25, 2010	E100131 Rev B Nov 19, 2013
					E100132 Rev A Jul 5, 2010	E100133 Rev A Sep 19, 2013
					E100134 Rev - Mar 29, 2010	E100135 Rev A Sep 19, 2013
					E100145 Rev B Sep 1, 2017	E100146 Rev C Sep 1, 2017
SA08-38 Issue 2 Jun 20, 2008	-	EASA.IM.A.S.02878 Rev 1 Dec 17, 2008	BEECH	Installation of Pitot Heat Indication System	FMS-1270-02 Issue 1 Jun 20, 2008	MMS-1270-02 Issue 1 Jun 2, 2008
			DHC-6-100, -200, -300			FMS-1270-01 Issue 1 Apr 7, 2008
SA07-131 Issue 2 Mar 12, 2010	-	EASA.IM.A.S.02729 Aug 13, 2008	DHC-6-100, -200, -300	Installation of Single or Dual Sandel SN4500 primary navigational display(s) (EHSI) with optional SA4550 primary attitude display(s) (EADI)	E100030 Rev A Nov 18, 2016	E100031 Rev B Nov 9, 2016
		10016400 Rev 1 Aug 3, 2010			E100032 Rev B Nov 18, 2016	E100033 Rev B Nov 9, 2016



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
SA07-65 Issue 5 Jun 2, 2017	SA03275NY Apr 29, 2013	-	DHC-6-100, -200, -300, -400	Installation of Supplemental Oxygen Systems	E104330 Rev C Dec 21, 2018	E104331 Rev E Nov 09, 2018
					E106830 Rev - May 26, 2017	E106831 Rev - Nov 15, 2016
SA07-59 Issue 1 May 7, 2007	-	-	DHC-6-100, -200, -300	Elevator and Rudder Access Panels	None	MMS-1206-01 Issue 1 May 3, 2007
SA06-53 Issue 1 Nov 14, 2006	SA03923NY Jun 6, 2017	-	DHC-6-100, -200, -300	Installation of Avionics Shelves In Tail	None	None
SA06-45 Issue 1 Jul 11, 2006	-	-	BEECH 200	Installation of a L-3 Communications - Avionics Recorders (Fairchild) A100S, or FA2100, or Universal CVR -30B Solid State Cockpit Voice Recorder (CVR)	None	195631 Rev - Feb 13, 2006
SA05-54 Issue 2 Mar 19, 2012	SA02204NY Jan 10, 2006	10042836 Dec 20, 2012	DHC-6-100, -200, -300	Installation of A L-3 Skywatch HP TCAS 1 System	E101430 Rev A Apr 19, 2013	E101431 Rev A Jan 26, 2013
SA04-52 Issue 1 Nov 2, 2004	SA02561NY Sep 2, 2008	-	BEECH 99 SERIES	Sandel ST3400 Terrain Awareness Warning System (TAWS) / RMI System	193730 Rev A Aug 25, 2008	193731 Rev A Jul 24, 2008 (FAA) 193732 Rev - Jun 29, 2004
SA02-128 Issue 3 Sep 26, 2012	SA01869NY Mar 16, 2004	EASA.IM.A.S.02129 Nov 3, 2006	DHC-6-100, -200, -300	Installation of a Single or Dual Sandel ST3400 Terrain Awareness Warning System (TAWS) / RMI System	E100330 Rev - Sep 14, 2012	E100331 Rev A Apr 10, 2013
		10015977 Rev 1 Mar 17, 2010			(EASA) E100372 Rev A Sep 20, 2011	
SA02-119 Issue 4 Dec 18, 2007	SA01885NY Mar 30, 2004	EASA.IM.A.S.02581 Rev 1 Nov 21, 2008	DHC-6-1, -100, -200, -300	Dual or Single Garmin GNS 530 / 530W or GNS 430 / 430W GPS / Nav / Comm system(s) for IFR Enroute, Terminal and Approach Operations	(Non-WAAS) 181830 Rev C Sep 14, 2005	(Non-WAAS) 181831 Rev C Sep 1, 2005
					(WAAS) 181833 Rev A Feb 10, 2017	(WAAS) 181834 Rev - Sep 21, 2007
					(FAA) 181832 Rev A Apr 23, 2004	(FAA) 181835 Rev - Sep 21, 2007
SA02-98 Issue 1 Sep 4, 2002	-	-	DHC-6-100, -200, -300	Aft Equipment Shelf Installation	None	None



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
SA02-25 Issue 1 Mar 15, 2002	-	-	DHC-6-100, -200, -300	Purge Hose Replacement	None	None
SA02-1 Issue 5 Jun 14, 2012	SA02387NY May 31, 2007	-	DHC-6-100,- 200, -300	Installation, Substitute Passanger Cabin and Cargo Baggage Floor Panels	None	E105331 Rev - Mar 16, 2012
SA01-135 Issue 1 Oct 31, 2001	-	-	DHC-6-100, -200, -300	Elevator Replacement Trailing Edge	None	None
SA01-76 Issue 1 Jun 27, 2001	SA01673NY May 14, 2003	-	DHC-6-100, -200	Installation of Pratt & Whitney PT6A-34 Engines with either Hartzell HC-B3TN-3D(Y) / T10282N(B) Propellers or McCauley RHFR34C764/94LMB-0 Propellers	FMS323101 Rev 2 Jun 27, 2001	MMS323101 Rev 1 May 30, 2001
SA01-30 Issue 2 Sep 27, 2016	SA02384NY May 21, 2007	EASA.IM.A.S.02198 Dec 22, 2006	DHC-6-100, -110, -200, -210, -300, -310, -320	Removal Of Auxiliary Battery	None	E118010 Rev - Aug 10, 2016
SA01-17 Issue 3 Jun 9, 2016	-	EASA.IM.A.S.02199 Oct 10, 2008	DHC-6-300	Cabin Evacuation Lighting Control System Change	E114030 Rev - Jun 8, 2016	None
SA98-67 Issue 1 Jun 29, 1998	-	-	Beech 99, 99A, A99, A99A	Installation of a Fairchild A100 or A100A Cockpit Voice Recorder	None	None
SA97-101 Issue 4 Oct 23, 2007	SA02297NY Aug 31, 2006	EASA.IM.A.S.02202 Oct 22, 2007	DHC-6-100, -200, -300	Cockpit Voice Recorder Installation	None	199031 Rev C Dec 10, 2015 (FAA) 199032 Rev C Dec 10, 2015
SA97-77 Issue 2 Nov 20, 2001	-	-	DHC-6-100, -200, -300	Replace Upper Fuselage Skin Panel	None	None
SA96-123 Issue 4 Mar 10, 2017	SA00837NY May 14, 1998	-	DHC-6-100, -200	Install Pratt & Whitney PT6A-27 Engines	D32891 Rev B Mar 9, 2017	D32871 Rev A Jan 27, 2017
SA96-110 Issue 1 Aug 1, 1996	SA03265NY Mar 27, 2013	10045940 Jul 30, 2013	DHC-6-300	Installation of PT6A-34 Engines Derated To 620 SHP in Lieu of PT6A-27 Engines	FMS966401 Rev - Aug 1, 1996	MMS966401 Rev - Aug 1, 1996
SE10-1 Issue 1 Jan 27, 2010	SE02837NY Aug 27, 2010	-	PT6A-21	Conversion of PT6A-21 to PT6A-28	None	None