



ROCKY MOUNTAIN AIRCRAFT

RMA STC SA15-49




NEW DHC-6 STC RADAR ALTIMETER MOUNTS

- Minor structural modification
- Reduce Labor by 80%

Was OEM Rad/Alt Structure:

Mod No. EO.68073

DWG. NO. C6FS3791



Major Structural Modifications

- Paint removal of large area for electrical bonding
- Fuselage stringer and skin
- Costly OEM parts
- Labour intensive

129 MacLaurin Drive

Calgary, AB

T3Z 3S4

(403)-288-3305

1-800-661-1130

rockystores@pathcom.ca

www.rockymountainaircraft.ca