




ROCKY MOUNTAIN AIRCRAFT

Corroded Pipes?

We have replacements!

Rocky Mountain Aircraft has identified the most problematic pipes and developed a set of PDA replacement pipes.



RMA-C6SC1150-1

PART NUMBER	
<u>ORIGINAL</u>	<u>PDA</u>
C6VF1173-1	RMA-C6VF1173-1
C6VF1078-1	RMA-C6VF1078-1
*C6VF1075-9	*RMA-C6VF1075-9
C6VF1075-3	RMA-C6VF1075-3
*C6SC1150-1	*RMA-C6SC1150-1 (PART OF RMA-C6VF1075-9)

RMA-C6VF1078-1



***RMA-C6VF1075-9**



RMA-CVF1173-1



RMA-C6VF1075-3



129 MacLaurin Drive
 Calgary, AB
 T3Z 3S4
 (403)-288-3305
 1-800-661-1130
 stores@rockymountainaircraft.ca
 www.rockymountainaircraft.ca